

The Structural Engineer



INDEX

Volume 76

1998

The Structural Engineer

JOURNAL OF THE INSTITUTION OF STRUCTURAL ENGINEERS

INDEX Volume 76, 1998

AUTHOR INDEX

A		Bussell, M N	
Abdul-Wahab, H M S		Investigation, appraisal and reuse of a cast-iron structural frame	37
Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271	Byfield, M P	
Ahmed, B	289	Material and geometric properties of structural steel for use in design – Correspondence	402
Plasticity of composite beams at serviceability limit state		C	
Allen, J D	175	Calavera, J	
Reengineering the design and construction process		For and against European certification	344
Sir Alfred Pugsley: An engineering genius – a man of quiet authority who never raised his voice – Tribute	205	Carper, K L	
Amodia, R M		Current structural safety topics in North America	233
The engineer in the marketplace – Viewpoint	93	Chapman, D K	
Arnold, P		Reading Football Club – Madjeski Stadium	419
Reading Football Club – Madjeski Stadium	419	Chapman, J C	
Austin, J A		Collapse of the Ramsgate Walkway	1
Over-design: fact or fiction?	17	Charrington, J P	
		Bridges for the Bridgend Cross Valley Link Road scheme	140
B		Cheong, H K	
Bailey, C G		Dynamic response of Republic Plaza, Singapore	221
The design of steel framed buildings without applied fire protection	77	Clark, L A	
Bainbridge, R J		Evolution or decay? – Presidential address	387
Stability bracing for non-domestic timber trussed rafter roofs . .	334	Serviceability limit state aspects of continuous bridges using precast concrete beams – Correspondence	202
Timber bridges – design and appropriate use of materials	313	Cole, G	
Timber floors: improvements through the reengineering process	319	Bridge load testing in Surrey	86
Bakht, B		Cook, N J	
Evaluation by proof of a T-beam bridge without drawings – Discussion	28	Comparing CP3 and BS 6399: Part 2 – ‘division by parts’ rule	115
		Comparing CP3 and BS 6399: Part 2 – ground roughness	65
Bamforth, S		Comparing CP3 and BS 6399: Part 2 – UK climate and design dynamic pressure	267
Professional indemnity insurance – the millennium problem . . .	343	Cottam, M P	
Barboutsis, C		Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator’s view – Discussion	240
Experimental research on the compressive strength of masonry repairs in Archeiropoietus Church, Thessaloniki	353	Crossin, J	
Beal, A N		The refurbishment of Westminster Bridge: bridge strengthening	195
Steelwork connections – Discussion	68	Currie, D M	
Beeby, A W		Gas explosions in the UK: regulation and risk	373
Ductility in reinforced concrete: why it is needed and how is it achieved? – Discussion	180	D	
Blakelock, R		Dallard, P	
The refurbishment of Westminster Bridge: assessment, design and precontract planning	189	Lattice shells: recent experiences – Open discussion	105
Booth, E D		Delpak, R	
A critical review of international practice on seismic design of reinforced concrete buildings	213	Structural R & D in Wales – Academia	144
Bowyer, A		Desai, S B	
Housing Grants, Construction and Regeneration Act, 1996: PII implications	304	Towards achieving competitive and sustainable concrete construction – Viewpoint	381
Brown, D G		Dibb-Fuller, D	
The impact of CIMsteel on the design process	46	Windsor Castle: fire behaviour and restoration aspects of historic ironwork	367
Brownjohn, J M W			
Dynamic response of Republic Plaza, Singapore	221	E	
Bullman, P J M		Edwards, S	
Edge-column connections in flat-slab construction	253	Verification of the robustness of a six-storey timberframe building	307

Elliott, K S		reaction – Discussion	25
Push-off tests on shear studs with hollow-cored floor slabs	167		
Ellis, B R		Analyses for creep of continuous steel and composite bridge	
Gas explosions in the UK: regulation and risk	373	beams according to EC4: Part 2.	294
Enjily, V		Johnston, J R	
Verification of the robustness of a six-storey timberframe building	307	Understanding your client's business is your success– Viewpoint	186
Evans, K W		K	
Design, build + finance: constructor or partner?.	149	Kappos, A J	
Everett, M		A critical review of international practice on seismic design of	
General Electric Aircraft Engine Services, GE90, Test Cell	121	reinforced concrete buildings.	213
F		Karaveziroglou-Weber, M	
Fewtrell, R		Experimental research on the compressive strength of masonry	
Windsor Castle: fire behaviour and restoration aspects of		repairs in Archeiropoietus Church, Thessaloniki	353
historic ironwork.	367	Kenward, J K	
Fraser, J S		Swansea Bay Sewage Treatment Works: structural design and	
Multistorey carpark, Orchard Street, Crawley, West Sussex	82	construction.	127
G		Knapton, J	
Garas, F K		The structural design of heavy duty pavements	153
CIMsteel (computer integrated manufacturing in constructional		Kong, F K	
steelwork) – delivering the promise	43	Fatigue tests of reinforced concrete deep beams.	347
Gardner, I		Kranas, B	
Engineering aspects of the UK pavilion Expo '92, Seville		Experimental research on the compressive strength of masonry	
. – Discussion	31	repairs in Archeiropoietus Church, Thessaloniki	353
Gordon, J A		Kumar, A	
Stability bracing for non-domestic timber trussed rafter roofs . .	334	Decks slab continuity for composite bridges.	447
Griffiths, D R		L	
Civil and structural engineering at the University of Surrey, Guildford	96	Lam, D	
Guard, M		Push-off tests on shear studs with hollow-cored floor slabs	167
Structural glass – Feature	11-12	Li, T Q	
H		Plasticity of composite beams at serviceability limit state	289
Hadden, D		Lin, L H	
Engineering aspects of the UK pavilion Expo '92, Seville	31	Structural hierarchy in spider webs and spiderweb-type systems	59
. – Discussion		Lindsell, P	
Hall, F A		Bridge load testing in Surrey	86
Glued laminated timber engineering	339	Luke, S J	
Hall, M		General Electric Aircraft Engine Services, GE90, Test Cell	121
Engineering aspects of the UK pavilion Expo '92, Seville		M	
. – Discussion	31	Ma, W A	
Hanswille, G		Fatigue tests of reinforced concrete deep beams.	347
Analyses for creep of continuous steel and composite bridge		Maguire, J R	
beams according to EC4: Part 2.	294	Hazards, risks and structural safety; hazard and risk assessment	
Harding, J E		in other industries; hazard and risk assessment for construction:	
Civil and structural engineering at the University of Surrey,		a regulator's view – Discussion	240
Guildford.	96	Male, S P	
Harris, T		The impact of CIMsteel on fabrication.	50
Engineering aspects of the UK pavilion Expo '92, Seville		Manning, M W	
. – Discussion	31-33	Lattice shells: recent experiences. – Open discussion	105
Hill, J A		Maranian, P	
The Institution beyond 2000	443	Vulnerability of existing steel framed buildings (following	
Hockaday, S		the 1994 Northridge (California, USA) earthquake:	
Design, build + finance: constructor or partner?.	149	considerations for their repair and strengthening).	227
Hughes, R F		Marshall, G R D	
Dr Francis Walley, CB, FEng. – Profile	91	The refurbishment of Westminster Bridge: bridge strengthening	195
Hunter, I		McElligott, M	
CIMsteel (computer integrated manufacturing in constructional		General Electric Aircraft Engine Services, GE90, Test Cell	121
steelwork) – delivering the promise	43	McQuillan, D	
The impact of CIMsteel on fabrication.	50	Raising the roof on Belfast Waterfront Hall – Discussion	159
J		McWilliams, R	
Jaeger, L G		Establishing business benefits through CIMsteel	56
Evaluation by proof of a T-beam bridge without drawings		Menzies, J B	
. – Discussion	28	Hazards, risks and structural safety; hazard and risk assessment	
Jayanetti, D L		in other industries; hazard and risk assessment for construction:	
Timber bridges – design and appropriate use of materials	313	a regulator's view. – Discussion	240
Johnson, R A		Mettem, C J	
The appraisal and maintenance of structures with alkali-silica		Stability bracing for non-domestic timber trussed rafter roofs . .	334
		Timber bridges – design and appropriate use of materials	313

Milner, M W		Robinson, M J	
Timber floors: improvements through the reengineering process	319	Investigation, appraisal and reuse of a cast-iron structural frame	37
Milner, M W		Roe, T	
Verification of the robustness of a six-storey timberframe building	307	88 Wood Street: stressful City office design	427
Mitrovic, D		Roulston, R N	
The impact of CIMsteel on fabrication	50	Raising the roof on Belfast Waterfront Hall – Discussion	159
Moore, D B		Rowbottom, D	
Steelwork connections – Discussion	68	'Just in time' construction at Ford	262
Munson, S R		Ryall, M J	
The refurbishment of Westminster Bridge: assessment, design and precontract planning	189	Civil and structural engineering at the University of Surrey, Guildford	96
N		S	
Neale, B S		Scott, I T	
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view – Discussion	240	Reading Football Club – Madjeski Stadium	419
Nethercot, D A		Smith, R A	
Material and geometric properties of structural steel for use in design – Correspondence	402	Practical advice for practising engineers – Viewpoint	143
Plasticity of composite beams at serviceability limit state	289	Smith, S	
Push-off tests on shear studs with hollow-cored floor slabs	167	88 Wood Street: stressful City office design	427
The impact of CIMsteel on the design process	46	Sobek, W	
Newman, G M		Structural hierarchy in spider webs and spiderweb-type systems	59
The design of steel framed buildings without applied fire protection	77	Sorley, A K	
Nicholson, B A		Bridges for the Bridgend Cross Valley Link Road scheme	140
Precast beams in continuous bridges	203	Stansfield, K	
Precast beams in continuous bridges – Correspondence	402	A moving experience [BNFL Floc Retrieval Project at Sellafield]	423
O		Intelligent buildings: the way forward	415
O'Brien, E J		Steele, A J	
Design and analysis of concrete slabs using a modified strip method	329	The impact of CIMsteel on fabrication	50
O'Dwyer, D W		Studer, T R	
Design and analysis of concrete slabs using a modified strip method	329	Stability bracing for non-domestic timber trussed rafter roofs	334
Owens, G W		Sugie, I	
Steelwork connections – Discussion	68	Serviceability limit state aspects of continuous bridges using precast concrete beams – Correspondence	202
P		Sun, B J	
Pan, T C		Rehabilitation of a grillage floor building – Technical note	22
Dynamic response of Republic Plaza, Singapore	221	Swan, M	
Park, R		'Just in time' construction at Ford	262
A critical review of international practice on seismic design of reinforced concrete buildings	213	Swift, R	
Parke, G A R		Windsor Castle: fire behaviour and restoration aspects of historic ironwork	367
Civil and structural engineering at the University of Surrey, Guildford	96	T	
Parker, D E		Tai, L Y	
Edge-column connections in flat-slab	253	Micropiles in Malaysia	299
Pope, D J		Tan, K H	
Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271	Fatigue tests of reinforced concrete deep beams	347
Povall, I B		Taylor, G D	
The Trafford Centre, Manchester – Discussion	438	Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271
Price, W F		Taylor, H P J	
Measurement and modelling of long-term creep in glued laminated timber beams used in structural building frames	271	The precast concrete bridge beam: the first 50 years	407
R		Teng, S	
Rawstron, A		Fatigue tests of reinforced concrete deep beams	347
Project documentation: taming the beast – Legal column	111	Tietz, S	
The Construction Act: changing the culture – Legal column	305	Risk analysis – uses and abuses	395
Reffold, A		Approved persons: insurance aspects – Feature	30
Stability bracing for non-domestic timber trussed rafter roofs	334	Ting, W H	
Reid, W M		Micropiles in Malaysia	299
Stadium structures – are they excited? – Discussion	258	Travers-Jones, E	
		Newport Wafer Fab – technology for the future	137
		Turnbull, D B	
		Verification of the robustness of a six-storey timberframe building	307
		W	
		Watermeyer, R	
		Socio-economic responsibilities – the contribution that structural engineers can make	283

Webster, M P	
Multistorey car parks – design and maintenance issues – Research matters	15
Whitby, M	
Establishing business benefits through CIMsteel	56
White, R	
88 Wood Street: stressful City office design.	427
Williams, M S	
Structural engineering at Oxford University.	246
Wood, J G M	
The appraisal and maintenance of structures with alkali- silica reaction. – Discussion	25
Woodward, D A	
The Trafford Centre, Manchester.	99
..... – Discussion	438
Wright, G	
‘Just in time’ construction at Ford	262
 Y	
Yeoll, D	
The refurbishment of Westminster Bridge: assessment, design and precontract planning	189
The refurbishment of Westminster Bridge:bridge strengthening .	195
 Z	
Zombou, A	
Experimental research on the compressive strength of masonry repairs in Archeiropoietus Church, Thessaloniki	353

A	
Accidental damage	
Verification of the robustness of a six-storey timberframe building	
Archeiropoietus Church, Thessaloniki	307
Experimental research on the compressive strength of masonry repairs in Archeiropoietus Church, Thessaloniki	
Adhesives	353
Glued laminated timber engineering	
Adjudication	339
Housing Grants, Construction and Regeneration Act, 1996: PII implications	
The Construction Act: changing the culture	304
Aesthetics	305
Multistorey carpark, Orchard Street, Crawley, West Sussex	
Aggregates	82
Towards achieving competitive and sustainable concrete construction	
Viewpoint	
Aldercastle, City of London	
The benefits of a partnering approach	
Alfred P Murrah Federal Building	383
Current structural safety topics in North America	
Amoco Building, Chicago	233
Current structural safety topics in North America	
Angel Street Bridge	233
Bridges for the Bridgend Cross Valley Link Road scheme	
Appraisal	140
Bridge load testing in Surrey	
Evaluation by proof of a T-beam bridge without drawings	
Discussion	
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view	28
Discussion	
Investigation, appraisal and reuse of a cast-iron structural frame	240
The appraisal and maintenance of structures with alkali-silica reaction	37
Discussion	
The refurbishment of Westminster Bridge: assessment, design and precontract planning	25
The refurbishment of Westminster Bridge: bridge strengthening	189
Windsor Castle: fire behaviour and restoration aspects of historic ironwork	195
Approved persons	367
Approved persons: insurance aspects	
Feature	
Arch bridges	30
Bridge load testing in Surrey	
The refurbishment of Westminster Bridge: assessment, design and precontract planning	86
The refurbishment of Westminster Bridge: bridge strengthening	189
Architecture	195
Structural glass	
Feature	
ASR	11
The appraisal and maintenance of structures with alkali-silica reaction	
Discussion	
B	
Basements	
'Just in time' construction at Ford	262
88 Wood Street: stressful City office design	427
Stainless steel reinforcement at Guildhall East, London	
Project	461
Swansea Bay Sewage Treatment Works: structural design and construction	127
Beams	
Analyses for creep of continuous steel and composite bridge beams according to EC4: Part 2	294
Evaluation by proof of a T-beam bridge without drawings	
Discussion	28
Glued laminated timber engineering	339
Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271
Plasticity of composite beams at serviceability limit state	289
Precast beams in continuous bridges	203
Correspondence	402
Rehabilitation of a grillage floor building	22
Technical note	
Serviceability limit state aspects of continuous bridges using precast concrete beams	202
Correspondence	407
The precast concrete bridge beam: the first 50 years	407
Vulnerability of existing steel framed buildings (following the 1994 Northridge (California, USA) earthquake: considerations for their repair and strengthening)	227
Bearings	
Collapse of the Ramsgate Walkway	1
Belfast Waterfront Hall	
Raising the roof on Belfast Waterfront Hall	159
Discussion	
Bending strength	
The structural design of heavy duty pavements	153
Biographies	
Dr Francis Walley, CB, FEng	91
Profile	
Sir Alfred Pugsley: an engineering genius – a man of quiet authority who never raised his voice	205
Tribute	
The President 1998-99 [Les Clark]	357
Profile	
Blast	
Gas explosions in the UK: regulation and risk	373
BNFL, Sellafield	
A moving experience [BNFL Flocc Retrieval Project at Sellafield]	423
Braced frames	
88 Wood Street: stressful City office design	427
Structural engineering at Oxford University	246
The Trafford Centre, Manchester	99
Discussion	438
Brewery River Bridge	
Bridges for the Bridgend Cross Valley Link Road scheme	140
Bridgend Cross Valley Link Road	
Bridges for the Bridgend Cross Valley Link Road scheme	140
Bridges (see also specific types of bridges)	
Analyses for creep of continuous steel and composite bridge beams according to EC4: Part 2	294
Bridges for the Bridgend Cross Valley Link Road scheme	140
Decks slab continuity for composite bridges	447
Evaluation by proof of a T-beam bridge without drawings	
Discussion	28
Precast beams in continuous bridges	203
Correspondence	402
Serviceability limit state aspects of continuous bridges using precast concrete beams	202
Correspondence	313
Timber bridges – design and appropriate use of materials bridges	407
The precast concrete bridge beam: the first 50 years	
Building Regulations	
Approved persons: insurance aspects	30
Feature	
Stadium structures – are they excited?	258
Discussion	307
Verification of the robustness of a six-storey timberframe building	
Building services	
Engineering aspects of the UK pavilion Expo '92, Seville	
Discussion	31
Building team	
The benefits of a partnering approach	383
Project	
C	
CAD	
Stadium structures – are they excited?	258
Discussion	99
The Trafford Centre, Manchester	348
Discussion	
Canada	
Evaluation by proof of a T-beam bridge without drawings	
Correspondence	28

Canalside West, Huddersfield		The impact of CIMsteel on the design process	46
Investigation, appraisal and reuse of a cast-iron structural frame	37	Columns	
Canopies		Edge-column connections in flat-slab construction	253
Structural glass – Feature	11	Investigation, appraisal and reuse of a cast-iron structural frame	37
Car parks		Vulnerability of existing steel framed buildings (following	
Multistorey carparks – design and maintenance issues	15	the 1994 Northridge (California, USA) earthquake:	
. – Research matters		considerations for their repair and strengthening).	227
Cast iron		Composite construction	
Bridge load testing in Surrey	86	Analyses for creep of continuous steel and composite bridge	
Investigation, appraisal and reuse of a cast-iron structural frame	37	beams according to EC4: Part 2	294
CDM Regulations		Decks slab continuity for composite bridges	447
CDM Regulations – the role of the designer – Briefing note	465	Plasticity of composite beams at serviceability limit state	289
Hazards, risks and structural safety; hazard and risk assessment		Push-off tests on shear studs with hollow-cored floor slabs	167
in other industries; hazard and risk assessment for construction:		The design of steel framed buildings without applied fire	
a regulator’s view – Discussion	240	protection	77
Ceilings		Concert halls	
Stability bracing for non-domestic timber trussed rafter roofs . .	334	Raising the roof on Belfast Waterfront Hall – Discussion	159
Cements		Concrete	
The structural design of heavy duty pavements	153	Self-compacting concrete – Report	462
Certification		The appraisal and maintenance of structures with alkali-silica	
For and against European certification	344	reaction – Discussion	25
Chek Lap Kok Airport, Hong Kong		The structural design of heavy duty pavements	153
Lattice shells: recent experiences – Open discussion	105	Connections	
Chimneys		CIMsteel (computer integrated manufacturing in constructional	
General Electric Aircraft Engine Services, GE90, Test Cell	121	steelwork) – delivering the promise	43
China		Developments in light-gauge steel construction – Industry view	425
Rehabilitation of a grillage floor building – Technical note	22	Edge-column connections in flat-slab construction	253
Churches		Steelwork connections – Discussion	68
Experimental research on the compressive strength of masonry		The impact of CIMsteel on the design process	46
repairs in Archeiropoietus Church, Thessaloniki	353	Vulnerability of existing steel framed buildings (following	
Cladding		the 1994 Northridge (California, USA) earthquake:	
Cladding – making the difference – Project	385	considerations for their repair and strengthening).	227
The benefits of a partnering approach – Project	383	Construction industry	
Claims		Design, build + finance: constructor or partner?	149
Housing Grants, Construction and Regeneration Act, 1996: PII		The Construction Act: changing the culture – Legal column	305
implications	304	The engineer in the marketplace – Viewpoint	93
Clark, Les		Professional indemnity insurance – the millennium problem	343
The President 1998-99 [Les Clark] – Profile	357	Contracts	
Clean rooms		Design, build + finance: constructor or partner?	149
Newport Wafer Fab – technology for the future	137	Housing Grants, Construction and Regeneration Act, 1996: PII	
Climate		implications	304
Comparing CP3 and BS 6399: Part 2 – UK climate and		The refurbishment of Westminster Bridge: bridge strengthening	195
design dynamic pressure	267	Corrosion	
Engineering a sustainable future [report on Maitland Lecture		Steel frame corrosion and building conservation – Report	464
given by Jonathan Porritt]	444	Costs	
Engineering aspects of the UK pavilion Expo ’92, Seville		Decks slab continuity for composite bridges	447
. – Discussion	31	Risk analysis – uses and abuses	395
Codes of practice		Swansea Bay Sewage Treatment Works: structural design and	
A critical review of international practice on seismic design		construction	127
of reinforced concrete buildings	213	Cracks	
Analyses for creep of continuous steel and composite		Fatigue tests of reinforced concrete deep beams	347
bridge beams according to EC4: Part 2	294	Ductility in reinforced concrete: why it is needed and how is	
Comparing CP3 and BS 6399: Part 2 – ‘division by parts’ rule . .	115	it achieved? – Discussion	180
Comparing CP3 and BS 6399: Part 2 – ground roughness	65	Precast beams in continuous bridges	203
Comparing CP3 and BS 6399: Part 2 – UK climate and design	 – Correspondence	402
dynamic pressure	267	Push-off tests on shear studs with hollow-cored floor slabs	167
Ductility in reinforced concrete: why it is needed and how is		Rehabilitation of a grillage floor building – Technical note	22
it achieved? – Discussion	180	Serviceability limit state aspects of continuous bridges using	
Edge-column connections in flat-slab construction	253	precast concrete beams – Correspondence	202
Fatigue tests of reinforced concrete deep beams	347	Creep	
Gas explosions in the UK: regulation and risk	373	Analyses for creep of continuous steel and composite bridge	
Hazards, risks and structural safety; hazard and risk assessment		beams according to EC4: Part 2	294
in other industries; hazard and risk assessment for construction:		Measurement and modelling of long term creep in glued	
a regulator’s view – Discussion	240	laminated timber beams used in structural building frames	271
Material and geometric properties of structural steel for use		Precast beams in continuous bridges	203
in design – Correspondence	402 – Correspondence	402
Push-off tests on shear studs with hollow-cored floor slabs	167	Crowds	
Stability bracing for non-domestic timber trussed rafter roofs . .	334	Stadium structures – are they excited? – Discussion	258
Stadium structures – are they excited? – Discussion	258	Curtain walls	
		Dynamic response of Republic Plaza, Singapore	221

D			
Decommissioning		by Jonathan Porritt]	444
A moving experience [BNFL Flocc Retrieval Project at Sellafield]	423	Intelligent buildings: the way forward	415
Deep beams		Europe	
Fatigue tests of reinforced concrete deep beams.	347	For and against European certification.	344
Design and build		Explosions	
Design, build + finance: constructor or partner?.	149	Gas explosions in the UK: regulation and risk	373
Detailing		F	
Multistorey carpark, Orchard Street, Crawley, West Sussex	82	Fabrics	
Serviceability limit state aspects of continuous bridges using precast concrete beams Correspondence	202	Engineering aspects of the UK pavilion Expo '92, Seville – Discussion	31
Diaphragms		Failures	
Decks slab continuity for composite bridges.	447	Collapse of the Ramsgate Walkway	1
Disputes		Current structural safety topics in North America	233
Housing Grants, Construction and Regeneration Act, 1996: PII implications.	304	Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view – Discussion	240
Project documentation: taming the beast – Legal column	111	Multistorey carparks – design and maintenance issues. – Research matters	15
The Construction Act: changing the culture – Legal column	305	The appraisal and maintenance of structures with alkali-silica reaction – Discussion	25
Documentation		Fatigue	
Project documentation: taming the beast – Legal column	111	Fatigue tests of reinforced concrete deep beams.	347
Domes		Fibre reinforced concrete	
Raising the roof on Belfast Waterfront Hall – Discussion	159	The structural design of heavy duty pavements	153
The Trafford Centre, Manchester – Discussion	438	Finance	
Ductility		Understanding your client's business is your success – Viewpoint	186
Ductility in reinforced concrete: why it is needed and how is it achieved? – Discussion	180	Design, build + finance: constructor or partner?.	149
Dunraven Place Footbridge		Finite element methods	
Bridges for the Bridgend Cross Valley Link Road scheme	140	Dynamic response of Republic Plaza, Singapore	221
Durability		Swansea Bay Sewage Treatment Works: structural design and construction	127
Glued laminated timber engineering. – Research matters	339	Fire	
Multistorey carparks – design and maintenance issues. – Update	15	Glued laminated timber engineering	339
Timber bridges – design and appropriate use of materials	313	Investigation, appraisal and reuse of a cast-iron structural frame	37
Dynamic loads		The design of steel framed buildings without applied fire protection	77
Gas explosions in the UK: regulation and risk	373	Windsor Castle: fire behaviour and restoration aspects of historic ironwork.	367
Newport Wafer Fab – technology for the future.	137	Firth Street Mills, Huddersfield	
Structural engineering at Oxford University.	246	Investigation, appraisal and reuse of a cast-iron structural frame	37
Stadium structures – are they excited? Discussion	258	Flat slabs	
E		Edge-column connections in flat-slab construction.	253
Earthquakes		Floors	
A critical review of international practice on seismic design of reinforced concrete buildings.	213	Over-design: fact or fiction?	17
Current structural safety topics in North America	233	Push-off tests on shear studs with hollow-cored floor slabs	167
Vulnerability of existing steel framed buildings (following the 1994 Northridge (California, USA) earthquake: considerations for their repair and strengthening).	227	Rehabilitation of a grillage floor building – Technical note	22
East Street Subway, Farnham, Surrey		The design of steel framed buildings without applied fire protection	77
Bridge load testing in Surrey	86	The navy takes flight – RNAS expansion, Yeovilton Project	459
Edge beams		Timber floors: improvements through the reengineering process	319
Multistorey carpark, Orchard Street, Crawley, West Sussex	82	Footbridges	
Education		Bridges for the Bridgend Cross Valley Link Road scheme	140
Civil and structural engineering at the University of Surrey, Guildford.	96	Ford Plant, Bridgend, Mid Glamorgan	
Evolution or decay?		'Just in time' construction at Ford	262
Presidential address	387	Forensic engineering	
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view. – Discussion	240	Current structural safety topics in North America	233
Investigation, appraisal and reuse of a cast-iron structural frame	37	Foundations	
Employment		88 Wood Street: stressful City office design.	427
Socio-economic responsibilities – the contribution that structural engineers can make	283	Frames	
The engineer in the marketplace – Viewpoint	93	A moving experience [BNFL Flocc Retrieval Project at Sellafield].	423
Encased beams		Collapse of the Ramsgate Walkway	1
The design of steel framed buildings without applied fire protection	77	Investigation, appraisal and reuse of a cast-iron structural frame	37
Environment		Reengineering the design and construction process	175
Engineering a sustainable future [report on Maitland Lecture given		Steel frame corrosion and building conservation. – Report	464
		The impact of CIMsteel on the design process.	46
		The navy takes flight – RNAS expansion, Yeovilton. Project	459
		Verification of the robustness of a six-storey timberframe building	307

Vulnerability of existing steel framed buildings (following the 1994 Northridge (California, USA) earthquake: considerations for their repair and strengthening)	227	Professional indemnity insurance – the millennium problem	343
		Project documentation: taming the beast – Legal column	111
G		Integer Millennium House	
GEA Engine Services Test Facility		Intelligent buildings: the way forward	415
General Electric Aircraft Engine Services, GE90, Test Cell	121	Integral bridges	
Glass		Deckslab continuity for composite bridges.	447
Structural glass. Feature	11	Intelligent buildings	
Glulam		Intelligent buildings: the way forward	415
Glued laminated timber engineering	339	Interviews	
Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271	Man of wood. Kathy Stansfield talks to Martin Milner at TRADA	436
Timber bridges - design and appropriate use of materials.	313	Iron	
Timber floors: improvements through the reengineering process	319	The refurbishment of Westminster Bridge: assessment, design and precontract planning	189
Governor's House, City of London		The refurbishment of Westminster Bridge: bridge strengthening	195
The benefits of a partnering approach – Project	383	Windsor Castle: fire behaviour and restoration aspects of historic ironwork	367
Greece		IStructE	
Experimental research on the compressive strength of masonry repairs in Archeiropoietus Church, Thessaloniki	353	Evolution or decay? – Presidential Address	387
Grillages		Notices and proceedings: AGM	302
Deckslab continuity for composite bridges.	447	Notices and proceedings [elections, transfers, etc.]	248
Rehabilitation of a grillage floor building. – Technical note	22	Notices and proceedings [elections, transfers, etc.]	469
Guildhall East, London		The Institution beyond 2000	443
Stainless steel reinforcement at Guildhall East, London – Project	461	Sam Thorburn's year – a safe pair of hands – Interview	358
		The President 1998-99 [Les Clark] – Profile	357
H		J	
Hazards		Japan	
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view – Discussion	240	A critical review of international practice on seismic design of reinforced concrete buildings.	213
Historic structures		Japan	
Windsor Castle: fire behaviour and restoration aspects of historic ironwork	367	Self-compacting concrete – Report	462
History		Joints	
Ductility in reinforced concrete: why it is needed and how is it achieved? – Discussion	180	Glued laminated timber engineering	339
Evolution or decay? – Presidential address	387	Vulnerability of existing steel framed buildings (following the 1994 Northridge California, USA) earthquake: considerations for their repair and strengthening).	227
The precast concrete bridge beam: the first 50 years	407	Joshua Hoyle Building, Manchester	
Timber bridges – design and appropriate use of materials	313	Steel frame corrosion and building conservation. – Report	464
Hollow core slabs		L	
Push-off tests on shear studs with hollow-cored floor slabs	167	L'Ambiance Plaza, Bridgeport Connecticut	
Hollow sections		Current structural safety topics in North America	233
The design of steel framed buildings without applied fire protection	77	Laboratories	
Hong Kong		Newport Wafer Fab – technology for the future	137
Lattice shells: recent experiences. – Open discussion	105	Laminates	
Housing		Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271
Developments in light-gauge steel construction – Industry view	425	Landscaping	
Structural glass. – Feature	11	Swansea Bay Sewage Treatment Works: structural design and construction Large building test facility	127
Housing Grants, Construction and Regeneration Act		Reengineering the design and construction process	175
Housing Grants, Construction and Regeneration Act, 1996: PII implications.	304	Lattice shells	
The Construction Act: changing the culture – Legal column	305	Lattice shells: recent experiences. – Open discussion	105
I		Law	
Industrial buildings		Approved persons: insurance aspects. – Feature	30
The navy takes flight – RNAS expansion, Yeovilton. – Project	459	Collapse of the Ramsgate Walkway	1
Industrialised building		For and against European certification.	344
Developments in light-gauge steel construction – Industry view	425	Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view – Discussion	240
Instrumentation		Housing Grants, Construction and Regeneration Act, 1996: PII implications.	304
Evaluation by proof of a T-beam bridge without drawings – Discussion	28	Professional indemnity insurance – the millennium problem	343
Insurance		Project documentation: taming the beast – Legal column	111
Approved persons: insurance aspects. – Feature	30	The Construction Act: changing the culture – Legal column	305
For and against European certification.	344	Leisure centres	
Housing Grants, Construction and Regeneration Act, 1996: PII implications.	304	The Trafford Centre, Manchester	99
	 – Discussion	438
		Liability	
		Collapse of the Ramsgate Walkway	1

Risk analysis – uses and abuses	395	Multistorey carparks – design and maintenance issues – Update	15
Lift slab construction		Verification of the robustness of a six-storey timberframe building	307
Current structural safety topics in North America	233	Vulnerability of existing steel framed buildings (following the 1994 Northridge California, USA) earthquake: considerations for their repair and strengthening).	227
Multistorey carparks – design and maintenance issues – Research matters	15	Murrayfield Stadium, Edinburgh	
Lifting		Stadium structures – are they excited? – Discussion	258
Raising the roof on Belfast Waterfront Hall – Discussion	159	N	
Lightweight concrete		National Centre for Popular Music, Sheffield	
The refurbishment of Westminster Bridge: assessment, design and precontract planning	189	Steel drums put Sheffield on the music map. – Project	386
The refurbishment of Westminster Bridge: bridge strengthening	195	Natural frequencies	
Limestone		Dynamic response of Republic Plaza, Singapore	221
Cladding – making the difference – Project	385	Nets	
M		Structural hierarchy in spider webs and spiderweb-type systems	59
Madjeski Stadium, Reading		New Zealand	
Reading Football Club – Madjeski Stadium.	419	A critical review of international practice on seismic design of reinforced concrete buildings.	213
Maintaining		Noise insulation	
Collapse of the Ramsgate Walkway	1	General Electric Aircraft Engine Services, GE90, Test Cell	121
Current structural safety topics in North America	233	Northern Ireland	
Multistorey carparks -design and maintenance issues – Research matters.	15	Raising the roof on Belfast Waterfront Hall – Discussion	159
Project documentation: taming the beast – Legal column	111	Northridge earthquake, Los Angeles	
The appraisal and maintenance of structures with alkali-silica reaction. – Discussion	25	Current structural safety topics in North America	233
Malaysia		Northridge, California	
Micropiles in Malaysia	299	Vulnerability of existing steel framed buildings (following the 1994 Northridge (California, USA) earthquake: considerations for their repair and strengthening).	227
Management		Norwich Southern Bypass	
Design, build + finance: constructor or partner?.	149	The precast concrete bridge beam: the first 50 years	407
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator’s view – Discussion	240	O	
The impact of CIMsteel on fabrication.	50	Office buildings	
Marketing		88 Wood Street: stressful City office design.	427
Understanding your client’s business is your success – Viewpoint	186	Cladding – making the difference – Project	385
Martin Milner		Over-design: fact or fiction?	17
Man of wood. Kathy Stansfield talks to Martin Milner at TRADA	436	Stainless steel reinforcement at Guildhall East, London – Project	461
Masonry		The navy takes flight – RNAS expansion, Yeovilton – Project	459
Experimental research on the compressive strength of masonry repairs in Archeiropietus Church, Thessaloniki	353	Offshore structures	
Multistorey carpark, Orchard Street, Crawley, West Sussex	82	Structural engineering at Oxford University.	246
Steel frame corrosion and building conservation. – Report	464	Old Wey Bridge, Surrey	
Masts		Bridge load testing in Surrey	86
Reading Football Club – Madjeski Stadium.	419	Organisations	
Materials		Glued laminated timber engineering	339
Multistorey carpark, Orchard Street, Crawley, West Sussex	82	Man of wood. Kathy Stansfield talks to Martin Milner at TRADA	436
The structural design of heavy duty pavements	153	P	
Towards achieving competitive and sustainable concrete construction. – Viewpoint	381	Parapets	
Modelling		The refurbishment of Westminster Bridge: assessment, design and precontract planning	189
Dynamic response of Republic Plaza, Singapore	221	Partitions	
Establishing business benefits through CIMsteel	56	Over-design: fact or fiction?	17
Measurement and modelling of long-term creep in glued laminated timber beams used in structural building frames	271	Partnering	
Monitoring		The benefits of a partnering approach – Project	383
Measurement and modelling of long term creep in glued laminated timber beams used in structural building frames	271	Pavements	
Stadium structures – are they excited? – Discussion	258	The structural design of heavy duty pavements	153
Structural engineering at Oxford University.	246	PFI	
The appraisal and maintenance of structures with alkali-silica reaction. – Discussion	25	Design, build + finance: constructor or partner?.	149
The refurbishment of Westminster Bridge:assessment, design and precontract planning	189	The engineer in the marketplace Viewpoint	93
Mortars		Piles	
Experimental research on the compressive strength of masonry repairs in Archeiropietus Church, Thessaloniki	353	88 Wood Street: stressful City office design.	427
Multistorey buildings		‘Just in time’ construction at Ford	262
Dynamic response of Republic Plaza, Singapore – Research matters	221	Micropiles in Malaysia	299
		Pipers Row, Wolverhampton	
		Multistorey carparks – design and maintenance issues – Research matters	15
		Planning	
		Professional indemnity insurance – the millennium problem . . .	343

The Institution beyond 2000	443	Ductility in reinforced concrete: why it is needed and how is it achieved? – Discussion	180
The impact of CIMsteel on fabrication.	50	Edge-column connections in flat-slab construction.	253
The refurbishment of Westminster Bridge: assessment, design and precontract planning	189	Evaluation by proof of a T-beam bridge without drawings – Discussion	28
The refurbishment of Westminster Bridge: bridge strengthening	195	Fatigue tests of reinforced concrete deep beams.	347
Ports		General Electric Aircraft Engine Services, GE90, Test Cell	121
Collapse of the Ramsgate Walkway Post tensioning.	1	Multistorey car parks – design and maintenance issues. – Update	15
88 Wood Street: stressful City office design.	427	Multistorey carpark, Orchard Street, Crawley, West Sussex	82
Rehabilitation of a grillage floor building. – Technical note	22	Precast beams in continuous bridges	203
Power stations		Precast beams in continuous bridges – Correspondence	402
A moving experience [BNFL Floc Retrieval Project at Sellafield].	423	Push-off tests on shear studs with hollow-cored floor slabs	167
Precast concrete		Reengineering the design and construction process	175
Precast beams in continuous bridges	203	Serviceability limit state aspects of continuous bridges using precast concrete beams – Correspondence	202
. – Correspondence	402	The design of steel framed buildings without applied fire protection	77
Serviceability limit state aspects of continuous bridges using precast concrete beams – Correspondence	202	The precast concrete bridge beam: the first 50 years	407
The precast concrete bridge beam: the first 50 years	407	The refurbishment of Westminster Bridge: assessment, design and precontract planning	189
Cladding – making the difference – Project	385	The refurbishment of Westminster Bridge: bridge strengthening	195
Multistorey carpark, Orchard Street, Crawley, West Sussex	82	Towards achieving competitive and sustainable concrete construction – Viewpoint	381
Multistorey car parks – design and maintenance issues – Research matters.	15	Reinforcement	
Precast beams in continuous bridges	203	Ductility in reinforced concrete: why it is needed and how is it achieved? – Discussion	180
Precast beams in continuous bridges – Correspondence	402	Serviceability limit state aspects of continuous bridges using precast concrete beams – Correspondence	202
Push-off tests on shear studs with hollow-cored floor slabs	167	Stainless steel reinforcement at Guildhall East, London – Project	461
The navy takes flight – RNAS expansion, Yeovilton – Project	459	Repair	
Prefabrication		Current structural safety topics in North America	233
Timber floors: improvements through the reengineering process	319	Experimental research on the compressive strength of masonry repairs in Archeiropoietus Church, Thessaloniki	353
Engineering aspects of the UK pavilion Expo '92, Seville – Discussion	31	The appraisal and maintenance of structures with alkali-silica reaction. – Discussion	25
Evaluation by proof of a T-beam bridge without drawings – Correspondence	28	Repairing	
Progressive collapse		Vulnerability of existing steel framed buildings (following the 1994 Northridge (California, USA) earthquake: considerations for their repair and strengthening).	227
Gas explosions in the UK: regulation and risk	373	Research	
Progressive collapse		Civil and structural engineering at the University of Surrey, Guildford.	96
Verification of the robustness of a six-storey timberframe building	373	Ductility in reinforced concrete: why it is needed and how is it achieved? – Discussion	180
Pugsley, Sir Alfred		Edge-column connections in flat-slab construction.	253
Sir Alfred Pugsley: an engineering genius – a man of quiet authority who never raised his voice – Tribute	205	Evolution or decay? – Presidential address	387
Purlins		Experimental research on the compressive strength of masonry repairs in Archeiropoietus Church, Thessaloniki	353
Reading Football Club – Madjeski Stadium.	419	Fatigue tests of reinforced concrete deep beams.	347
Q		Gas explosions in the UK: regulation and risk	373
Quality		Investigation, appraisal and reuse of a cast-iron structural frame	37
Towards achieving competitive and sustainable concrete construction. – Viewpoint	381	Man of wood. Kathy Stansfield talks to Martin Milner at TRADA	436
R		Over-design: fact or fiction?	17
Railbridges		Plasticity of composite beams at serviceability limit state	289
Bridges for the Bridgend Cross Valley Link Road scheme	427	Push-off tests on shear studs with hollow-cored floor slabs	167
Railways		Reengineering the design and construction process	175
88 Wood Street: stressful City office design.	427	Self-compacting concrete – Report	462
Ramps		Stadium structures – are they excited? – Discussion	258
Collapse of the Ramsgate Walkway	1	Structural R & D in Wales. – Academia	144
Ramsgate walkway		Structural engineering at Oxford University.	246
Collapse of the Ramsgate Walkway	1	The design of steel framed buildings without applied fire protection	77
Recycling		Verification of the robustness of a six-storey timberframe building	307
'Just in time' construction at Ford	262	Restoring	
Towards achieving competitive and sustainable concrete construction. Viewpoint	195	Steel frame corrosion and building conservation – Report	464
The refurbishment of Westminster Bridge: bridge strengthening	195	The refurbishment of Westminster Bridge: assessment, design and precontract planning	189
Reinforced concrete		Windsor Castle: fire behaviour and restoration aspects of historic	
88 Wood Street: stressful City office design.	427		
A critical review of international practice on seismic design of reinforced concrete buildings.	86		
Bridge load testing in Surrey	447		
Decks slab continuity for composite bridges.	447		
Design and analysis of concrete slabs using a modified strip method	329		

ironwork	367	method	329
Risk		Multistorey carpark, Orchard Street, Crawley, West Sussex	82
Gas explosions in the UK: regulation and risk	373	Push-off tests on shear studs with hollow-cored floor slabs	167
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view	240	Rehabilitation of a grillage floor building – Technical note	22
Risk analysis – uses and abuses	395	The design of steel framed buildings without applied fire protection	77
River Frome Bridge		Slimdeck	
Deckslab continuity for composite bridges	447	The design of steel framed buildings without applied fire protection	77
Robustness		Slimflor	
Ductility in reinforced concrete: why it is needed and how is it achieved?	180	The design of steel framed buildings without applied fire protection	77
Verification of the robustness of a six-storey timberframe building	307	Software	
Roofs		Establishing business benefits through CIMsteel	56
'Just in time' construction at Ford	262	Professional indemnity insurance – the millennium problem	343
Engineering aspects of the UK pavilion Expo '92, Seville	31	The impact of CIMsteel on fabrication	50
		The impact of CIMsteel on the design process	46
Lattice shells: recent experiences	105	Spain	
Raising the roof on Belfast Waterfront Hall	159	Engineering aspects of the UK pavilion Expo '92, Seville	31
Reading Football Club – Madjeski Stadium	419		
Stability bracing for non-domestic timber trussed rafter roofs	334	Spiders webs	
Steel drums put Sheffield on the music map	386	Structural hierarchy in spider webs and spiderweb-type systems	59
Swansea Bay Sewage Treatment Works: structural design and construction	127	Sports grounds	
Rotation capacity		Stadium structures – are they excited?	258
Ductility in reinforced concrete: why it is needed and how is it achieved?	180	St Martins Bridge, Stamford	
Royal Naval Air Station, Yeovilton		The precast concrete bridge beam: the first 50 years	407
The navy takes flight – RNAS expansion, Yeovilton	459	Stability	
S		88 Wood Street: stressful City office design	427
Safety		Engineering aspects of the UK pavilion Expo '92, Seville	31
A moving experience [BNFL Floc Retrieval Project at Sellafield]	423		
Collapse of the Ramsgate Walkway	1	Evaluation by proof of a T-beam bridge without drawings	28
Hazards, risks and structural safety; hazard and risk assessment in other industries; hazard and risk assessment for construction: a regulator's view	240		
Sandy Creek Bridge, Ontario		Stability bracing for non-domestic timber trussed rafter roofs	334
Evaluation by proof of a T-beam bridge without drawings	28	The design of steel framed buildings without applied fire protection	77
Sculptures		Stadia	
Cladding – making the difference	385	Reading Football Club – Madjeski Stadium	419
Seatings		Stadium structures – are they excited?	258
Serviceability limit state aspects of continuous bridges using precast concrete beams	202	Stainless steel	
		Stainless steel reinforcement at Guildhall East, London	461
Serviceability			
Plasticity of composite beams at serviceability limit state	289	Steel drums put Sheffield on the music map	386
Serviceability limit state aspects of continuous bridges using precast concrete beams	202	Stairs	
The appraisal and maintenance of structures with alkali-silica reaction	25	88 Wood Street: stressful City office design	427
Sewage treatment works		Structural glass	11
Swansea Bay Sewage Treatment Works: structural design and construction	127	Steel	
Shear		'Just in time' construction at Ford	262
Edge-column connections in flat-slab construction	253	88 Wood Street: stressful City office design	427
Fatigue tests of reinforced concrete deep beams	347	A moving experience [BNFL Floc Retrieval Project at Sellafield]	423
Push-off tests on shear studs with hollow-cored floor slabs	167	Analyses for creep of continuous steel and composite bridge beams according to EC4: Part 2	294
Shopping centres		CIMsteel (computer integrated manufacturing in constructional steelwork) – delivering the promise	43
The Trafford Centre, Manchester	99	Developments in light-gauge steel construction – Industry view	425
		Engineering aspects of the UK pavilion Expo '92, Seville	31
Singapore			
Dynamic response of Republic Plaza, Singapore	221	Establishing business benefits through CIMsteel	56
Site investigation		Evaluation by proof of a T-beam bridge without drawings	28
Swansea Bay Sewage Treatment Works: structural design and construction	127		
Slabs		Material and geometric properties of structural steel for use in design	402
88 Wood Street: stressful City office design	427	Raising the roof on Belfast Waterfront Hall	159
Design and analysis of concrete slabs using a modified strip		Reading Football Club – Madjeski Stadium	419
		Steel drums put Sheffield on the music map	386
		Steel frame corrosion and building conservation	464
		Steelwork connections	68
		The Trafford Centre, Manchester	99
		The impact of CIMsteel on fabrication	50

The impact of CIMsteel on the design process	46	laminated timber beams used in structural building frames	271
The navy takes flight – RNAS expansion, Yeovilton . . . – Project	459	Stability bracing for non-domestic timber trussed rafter roofs . .	334
Vulnerability of existing steel framed buildings (following		Timber bridges – design and appropriate use of materials	313
the 1994 Northridge (California, USA) earthquake:		Timber floors: improvements through the reengineering process	319
considerations for their repair and strengthening).	227	Verification of the robustness of a six-storey timberframe building	307
Windsor Castle: fire behaviour and restoration aspects of		TRADA	
historic ironwork	367	Man of wood. Kathy Stansfield talks to Martin Milner at TRADA	436
Strategic Plan Task Group		Transfer structures	
The Institution beyond 2000	443	88 Wood Street: stressful City office design.	427
Strengthening		Trusses	
Investigation, appraisal and reuse of a cast-iron structural frame	37	Stability bracing for non-domestic timber trussed rafter roofs . .	334
Rehabilitation of a grillage floor building – Technical note	22	Engineering aspects of the UK pavilion Expo '92, Seville	31
The refurbishment of Westminster Bridge: assessment, design	 – Discussion	
and precontract planning	189	Raising the roof on Belfast Waterfront Hall – Discussion	159
The refurbishment of Westminster Bridge: bridge strengthening	195	Reading Football Club – Madjeski Stadium.	419
Vulnerability of existing steel framed buildings (following		Tubes	
the 1994 Northridge (California, USA) earthquake:		Engineering aspects of the UK pavilion Expo '92, Seville	
considerations for their repair and strengthening).	227 – Discussion	31
Strip method		Evaluation by proof of a T-beam bridge without drawings	
Design and analysis of concrete slabs using a modified strip	 – Discussion	28
method	329	Reading Football Club – Madjeski Stadium.	419
Sustainability		Tunnel Bridge, Surrey	
Engineering a sustainable future [report on Maitland Lecture given		Bridge load testing in Surrey	86
by Jonathan Porritt]	444	U	
Towards achieving competitive and sustainable concrete		UK Pavilion, Expo '92 Seville	
construction – Viewpoint	381	Engineering aspects of the UK pavilion Expo '92, Seville	31
Swansea Bay Sewage Treatment Works	 – Discussion	
Swansea Bay Sewage Treatment Works: structural design and		Universities	
construction.	127	Structural R & D in Wales – Academia	144
T		Civil and structural engineering at the University of Surrey,	
Tanks		Guildford.	96
A moving experience [BNFL Floc Retrieval Project at Sellafield].	423	Measurement and modelling of long-term creep in glued	
Teaching		laminated timber beams used in structural building frames	271
Structural engineering at Oxford University.	246	Structural engineering at Oxford University.	246
Tension structures		USA	
Engineering aspects of the UK pavilion Expo '92, Seville		A critical review of international practice on seismic design of	
. – Discussion	31	reinforced concrete buildings.	213
Evaluation by proof of a T-beam bridge without drawings		Current structural safety topics in North America	233
. – Discussion	28	Vulnerability of existing steel framed buildings (following	
Structural hierarchy in spider webs and spiderweb-type systems	59	the 1994 Northridge (California, USA) earthquake:	
Testing		considerations for their repair and strengthening).	227
Bridge load testing in Surrey	86	V	
Edge-column connections in flat-slab construction.	253	Ventilation	
Evaluation by proof of a T-beam bridge without drawings		Steel drums put Sheffield on the music map. – Project	386
. – Discussion	28	Vibration	
Fatigue tests of reinforced concrete deep beams.	347	Newport Wafer Fab – technology for the future.	137
Push-off tests on shear studs with hollow-cored floor slabs	167	Stadium structures – are they excited? – Discussion	258
Stability bracing for non-domestic timber trussed rafter roofs . .	334	W	
The refurbishment of Westminster Bridge: assessment, design		Wales	
and precontract planning	189	Bridges for the Bridgend Cross Valley Link Road scheme	140
Bridge load testing in Surrey	86	General Electric Aircraft Engine Services, GE90, Test Cell	121
Evaluation by proof of a T-beam bridge without drawings		'Just in time' construction at Ford	262
. – Discussion	28	Newport Wafer Fab – technology for the future	137
Fatigue tests of reinforced concrete deep beams.	347	Structural R & D in Wales. – Academia	144
Plasticity of composite beams at serviceability limit state	289	Swansea Bay Sewage Treatment Works: structural design and	127
Push-off tests on shear studs with hollow-cored floor slabs	167	construction.	
Stability bracing for non-domestic timber trussed rafter roofs . .	334	Walley, Francis	
Stadium structures – are they excited? – Discussion	258	Dr Francis Walley, CB, FEng – Profile	91
The refurbishment of Westminster Bridge: assessment, design		Welding	
and precontract planning	189	Vulnerability of existing steel framed buildings (following	
Verification of the robustness of a six-storey timberframe building	307	the 1994 Northridge (California, USA) earthquake:	
Windsor Castle: fire behaviour and restoration aspects of		considerations for their repair and strengthening).	227
historic ironwork	367	Westminster Bridge, London	
Thorburn, Sam		The refurbishment of Westminster Bridge:assessment, design	
Sam Thorburn's year – a safe pair of hands – Interview	358	and precontract planning	189
Timber		The refurbishment of Westminster Bridge:bridge strengthening .	195
Man of wood. Kathy Stansfield talks to Martin Milner at TRADA	436		
Measurement and modelling of long term creep in glued			

Westway, London	
The precast concrete bridge beam: the first 50 years	407
Wind loads	
Comparing CP3 and BS 6399: Part 2 -- 'division by parts' rule.	115
Comparing CP3 and BS 6399: Part 2 -- UK climate and design	267
dynamic pressure.	
Reading Football Club -- Madjeski Stadium.	419
Windsor Castle	
Windsor Castle: fire behaviour and restoration aspects of	
historic ironwork	367
Y	
Y beams	
The precast concrete bridge beam: the first 50 years	407
Yield line methods	
Design and analysis of concrete slabs using a modified strip	
method	329